

# S400 Firmware changelog

## Note

Please read the update instructions carefully before updating the machine. Failure to follow the update procedure correctly may result in machine damage.

## Version history

Only major changes that affect the machine's functionality are reported here. Please note that minor bug fixes and internal improvements may also be included in each update.

Version numbers not listed here are pre-production, test, beta, or special versions. If your machine has one of these, contact service for information before updating.

### ***Version 1.00 – Initial Release***

### ***Version 1.01 – December 2023***

- Fixed an issue with arc ignition when using a simple wire feeder suitcase with analog control, which caused the wire to touch and push the torch before starting the arc.

### ***Version 1.02 – January 2024***

- Improved the start in MIG 2TS/4TS, particularly at medium to high wire feed speeds.

### ***Version 1.03 – February 2024***

- Added three pulsed programs for Mild Steel wires with M20 gas (requires an F40 with firmware version 1.07 or later to recall these programs);
- Enhanced the double-pulsed process, especially at low speeds.

### ***Version 1.04 – July 2024***

- Fixed an issue in torch calibration that caused the calibration correction not be applied in certain cases;
- Fixed the voltage reading in pulsed mode: now the machine shows the correct arc voltage.