

F40 Firmware changelog

Note

Please read the update instructions carefully before updating the machine. Failure to follow the update procedure correctly may result in machine damage.

Starting from BD-382491 the machines are equipped with the new logic board with integrated USB instead of the dedicated programmer board, this is visible in the “Information” screen, the hardware version is 1 (HW: 1).

Version history

Only major changes that affect the machine's functionality are reported here. Please note that minor bug fixes and internal improvements may also be included in each update.

Version numbers not listed here are pre-production, test, beta, or special versions. If your machine has one of these, contact service for information before updating.

Version 1.00 – Initial Release

Version 1.03 – October 2023

- Corrected translation errors in “Torch calibration” screen;
- Fixed a bug with digital torch that sometimes causes the recall a wrong job number (eg. JOB 255);
- Added “5” to “AlMg” and “AlSi” wire labels;
- Added the “CC” alarm message in case of short-circuit on the welding output;
- Added the automatic recognition of the hardware version of the F40 logic board and error message if the hardware is not compatible;
- Improved immunity against HF disturbance;
- Added the possibility to launch a software update after few seconds, if the wire feeder is stuck in the “splash” screen due to some errors;
- Improved error diagnostic on the startup with updated error codes.

Version 1.04 – November 2023

- Fixed a bug that causes the thickness in double pulse mode to remain displayed incorrectly when the double pulse program was recalled with the torch;
- Fixed a bug that caused the wire feeder to display coded error messages when a temperature sensor failed, instead of a descriptive message;
- Extended the BurnBack regulation to 200%;

- Added a confirmation request before overwriting an existing saved job;

Version 1.07 – February 2024

- Fixed a bug that causes the 4T trigger mode to be not available in manual MIG;
- Fixed a bug where the restore confirmation message was displayed instead of the job overwrite confirmation message;
- Fixed a bug: now the “NO” key is working properly in the restore/overwrite job screens;
- Added some more information in the alarm popup to help troubleshooting;
- Added 3 pulsed programs for Mild Steel with M20 gas (only available with an S400 with version 1.03 or higher);

Version 1.08 – September 2024

- Updated the software to be compatible with logic board with hardware revision 1 (E1254);
- Fixed a bug in the main screen that, in some cases, caused some symbols to disappear;
- Improved the alarm description of primary current problem;
- Improved the precision of the torch calibration results shown in the display;
- Now at the end of the torch calibration procedure, the compensation setting goes automatically in “MEASURED”;
- Now a message is shown if you set the machine to MEASURED but do not immediately perform a torch calibration;
- Other internal improvements to support future updates and power source models;